


1

80 40 1730 1810 80 404 444



= 2500 + N.A.P

te maken liftput

Peil = 0

BESTAANDE FUNDERING.

2500+P
2400+P
1700+P
1600+P
1350+P
1250
1000
1000-P

BESTAANDE BESTRAGING

1700+P

1350+P
1250+P
720+P
470+P
Peil = 0
1000
1000-P

300 165 1663 250 267

Doorsnede 5