







Electrolyser ground floor_IT




Annex building ground floor_IT




Annex building first floor_IT



Annex building second floor_IT



Workshop ground floor_IT



Polishing unit ground floor_IT

Integrale toegankelijkheid

- Yes
- No

Integrale toegankelijkheid	
Name	Integrale toegankelijkheid
Battery room	No
Cable room	No
First aid point	No
hVAC	No
Instrument cabinet room	No
Polishing Unit	No
Process Hall	No
Staircase	No
Staircase	No
Staircase	No
Substation 1	No
Toilet	No
Warehouse	No
Workshop 1	No
Workshop 2	No

Integrale toegankelijkheid

project HH1
werk.nr. 3258_01
tek.nr. KA IT-01-200
tek.nr. WR Checker
tek.nr. SH Approver
datum 21-04-2022

schaal 1:200 A1
status Definitive
revisie
fase